### Montana Tech Library

## Digital Commons @ Montana Tech

Silver Bow Creek/Butte Area Superfund Site

Montana Superfund

Summer 7-7-2021

# BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

Nikia Greene Environmental Protection Agency

Atlantic Richfield Company

**Butte Silver Bow** 

Follow this and additional works at: https://digitalcommons.mtech.edu/superfund\_silverbowbutte

Part of the Environmental Health and Protection Commons, Environmental Indicators and Impact Assessment Commons, and the Environmental Monitoring Commons

#### **Recommended Citation**

Greene, Nikia; Atlantic Richfield Company; and Butte Silver Bow, "BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)" (2021). *Silver Bow Creek/Butte Area Superfund Site*. 402.

https://digitalcommons.mtech.edu/superfund\_silverbowbutte/402

This Government Report is brought to you for free and open access by the Montana Superfund at Digital Commons @ Montana Tech. It has been accepted for inclusion in Silver Bow Creek/Butte Area Superfund Site by an authorized administrator of Digital Commons @ Montana Tech. For more information, please contact sjuskiewicz@mtech.edu.

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

### **EPA REGION 8 OA DOCUMENT REVIEW CROSSWALK**

				-	DOCUMENT REVIEW	R.			
QAPP/FSP		Ent	<b>tity</b> (grante	ee, contract, EPA AO,	EPA Program, Other)	Regulatory	2 CFR 1500 for		
(check appropriate box)       GRANTEE       BSB County and AR						Authority	Grantee/Cooperative Agreements		
		BSI	B County a	and AR		- /	48 CFR 46 for Contracts		
CC	NTRACTOR					and/or	Interagency Agreement		
EP	Α						EPA/Court Order		
Ot	her					Funding	EPA Program Funding		
						Mechanism	EPA Program Regulation		
							EPA CIO 2105		
Document 7		BPS	SOU Draft	Final Residential Me	tals Abatement Program				
	ill be repeated in He		/ ~	PP (Non-Residential P	Parcels) (7/7/2021)				
QAPP/FSP	SAP Preparer	AR	and BSB (	County					
Period of P	erformance	202	21			Date Submitted	7/7/21		
(of QAPP/FSP)						for Review			
EPA Project Officer Nikia Greene						PO Phone #			
EPA Project Manager						PM Phone #			
QA Program Reviewer or Nikia Greene						Date of Review	7/8/21		
Approving									
Documen	ts Submitted f	for QAPP I	Review (	QA Reviewer must	Notes for Document Submitt				
complete):					<ol> <li>A QAPP written by a Grantee, EPA, or Federal Partner <u>must include</u> for review: Work Plan(WP) / Statement of Work (SOW) / Program Plan (PP) / Research Proposal</li> </ol>				
· · · · · · · · · · · · · · · · · · ·	ument(s) submit	tted for revie	ew:						
QA	Document	Document		Document with	(RP) and funding mechanis				
Document	Date	Stand-alor	ne (	QAPP		tten by Contractor must include for review:			
QAPP	7/7/21	Yes / No				opy of Task Order Work Assignment/SOW			
FSP		Yes / No	×.	Yes / No		electronic copy of the contractor's approved QMP if no QMP has been approved			
SAP		Yes / No	Y	Yes / No			approved		
SOP(s)	(attached)		Y	Yes / No	<ul><li>d) Copy of EPA/Court Order, if applicable</li><li>e) The QA Review must determine (with the EPA CO or PO) if a QARF was completed</li></ul>				
2. WP/SOV	V/TO/PP/RP Da	ate			for the environmental data activity described in the QAPP.				
WP/SOV	V/TO/RP Perfo	rmance Peri	iod		<b>3. a</b> . Field Sampling Plan (FSP) and/or Sampling & Analyses Plan (SAP) must include the				
3. QA document consistent with the:					Project QAPP <u>or must be a stand-alone QA document that <u>contain all QAPP required</u></u>				
WP/SOW/PP for grants? <u>Yes / No</u>					elements (Project Management, Data Generation/Acquisition, Assessment and				
SOW/TO for contracts? Yes / No					Oversight, and Data Validation and Usability).				
4. QARF signed by R8 QAM <u>Yes / No / NA</u>					<b>c.</b> SOPs must be submitted with a QA document that <u>contains all QAPP required</u>				
Funding Mechanism <u>IA / contract / grant / NA</u>					elements.				
Amount	t	_							
Summary	f Comments (hi	iahliaht sianit	ficant conc	parns/issuas).	Ш				
Summary		Sungin signij		cins/ 1001100 / •					

1. A QAPP is a formal document describing in comprehensive detail the necessary QA, QC, and other technical activities that must be implemented to ensure the results of the work performed will satisfy the stated performance criteria. The QAPP must be a stand-alone document that specifies the project's technical and quality objectives, the intended measurements, data generation, and data acquisition methods appropriate for achieving project objectives. A few references to

Page 1 of 28

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

external documents have been made in this version of the QAPP. The information contained in these external references need to be included in the QAPP and not rely on finding or obtaining the external document. Another deficiency is the lack of discussion of field QC measures and sampling. Please eliminate all reference to the CFRSSI documents/standard operating procedures and include stand-alone support documentation specific to these data collection activities. In addition, please include a reference to the BPSOU Data Management Plan, which EPA and DEQ are currently reviewing (note: the review is an annual update review).

Atlantic Richfield Response (6/7/21): Field QC measures and project-specific standard procedures have been included in the revised document. Reference to the CFRSSI documents and SOPs has been removed from the plan. The BPSOU Data Management Plan was submitted to the Agencies for review and comment on December 22, 2017, and later approved in June 26, 2018.

EPA: Resolved. (6/16/21)

2. As a critical component of the ROD, documenting all RMAP activities is important. This includes noting site deficiencies, preparing corrective actions, management of data including the use of existing data, and tracking site progress. This information is critical to EPA's ability to assess whether BPSOU ROD remedial action objectives are being met, and the RMAP must describe how records of these activities will be kept and maintained. Further, EPA must have access to the data collected under this QAPP and the ability to access and determine the status and records of the RMAP.

Atlantic Richfield Response (6/7/21): Section 2.9 in the revised QAPP describes documents and records. The RMAP database has been developed and is in use. The database is available for Agency access and additional comments and functionality requests. Atlantic Richfield and Butte-Silver Bow would like to coordinate Agency testing of the database with the program architects and primary users in a manner to minimize provision of written comment, and the potential misinterpretation of those comments. Ideally, this coordinated review and testing would occur concurrently with the Agencies review of the two separate RMAP QAPPs (residential and non-residential).

EPA: Resolved. (6/16/21)

3. In 2011, the Explanation of Significant Differences added the Expanded Area to allow for attic sampling of residential properties outside of the BPSOU as part of the RMAP. With the recent attention given to the West Side Soils Operable Unit, EPA proposes to address contamination concerns outside of the BPSOU to allow for residential yard soil, interior living space dust, and lead-based paint sampling to occur as-needed or by request in the Expanded Area. Sampling adjacent areas outside of the Expanded Area will be permitted on a case-by-case basis. Please modify the RMAP QAPP to include all sampling types within the Expanded Area (and adjacent to the Expanded Area case-by-case) after receiving a request or a development proposal that could lead to a potential exposure pathway at a residential property.

Atlantic Richfield Response (6/7/21): Atlantic Richfield and Butte-Silver Bow have agreed to expansion of the RMAP to the geographic extent indicated on Figure 1. Testing of properties outside of the BPSOU boundary (see Figure 1), yet falling within the 2020 RMAP Area, will be performed on a "by request" basis as defined in the RMAP Plan and QAPP.

EPA: Resolved. (6/16/21)

4. As discussed further below, additional sampling efforts are needed for parks and play areas within the BPSOU and to address residential properties or sections where soil sampling may only have occurred in the 0-2 inch depth interval. In addition, updating and clarification on the data validation requirements is needed.

Atlantic Richfield Response (6/7/21): Section 3.2.3 describes previously sampled properties that were sampled to a 0-2 inch depth. Section 6.0 in the revised QAPP describes the proposed data validation process.

Atlantic Richfield and Butte-Silver Bow have also agreed to include parks, play areas, schools, and commercial properties with residential living spaces within the RMAP. Discussion of these program additions are provided in Section 3.2 (schools, parks, and non-residential daycares). Commercial properties with residential living spaces will be addressed in the forthcoming RMAP Residential Parcels QAPP.

EPA: Resolved. (6/16/21)

5. The QAPP needs to clarify whether XRF or EPA methodologies will be used to analyze soil sampling within the RMAP. The QAPP seems to mostly specify that EPA standard methods will be used to analyze soils except in a few instances. For example, Sections 2.6.2, 3.8.3, and 7 have conflicting statements on which analytical method will be used for soils. Importantly, if XRF will be used to analyze soils, significant additions to the QAPP will be necessary. This includes a procedure for XRF sample preparation and analysis, submission of confirmation samples to establish XRF/wet laboratory correlations, evaluation of calibration verification checks against standard reference materials, and establishing an alternate XRF action level to limit remediation errors.

# Atlantic Richfield Response (6/7/21): XRF is not proposed for non-residential parcel soil analysis. The QAPP has been revised to clarify and eliminate conflicting statements.

EPA: Resolved. (6/16/21)

6. Further details for the sampling of parks, schools, and commercial properties should be added to the QAPP. EPA anticipates that sampling these locations will be based on site-specific conditions. Please specify that EPA will be notified prior to the sampling of parks, schools, and commercial properties.

Atlantic Richfield Response (6/7/21): Section 3.2 (schools, parks, and non-residential daycares) in the revised QAPP describes additional sampling in these areas previously excluded from RMAP. Commercial properties with residential living spaces will be addressed in the forthcoming RMAP Residential Parcels QAPP.

EPA: Resolved. (6/16/21)

7. AR/BSB County should expect that revisions to the RMAP QAPP will be necessary on an annual basis. EPA anticipates that the effort to produce the updated RMAP QAPP will be reduced as refinements are made each year.

Atlantic Richfield Response (6/7/21): Atlantic Richfield Response: The QAPP will be reviewed annually and updates completed as needed to accurately reflect program needs.

EPA: Resolved. (6/16/21)

8. The BSB County and AR must address the comments in the Summary of Comments, as well as those identified in the Comment section(s) that includes a "Response (date)" and Resolved (date)". In the crosswalk below, please provide your response in a different text color. All EPA crosswalk comments have been resolved (7/8/21)

Element	Acceptable Yes/No/NA	Page/ Section	Comments		
A. Project Management					
A1. Title and Approval Sheet					

a. Contains project title	Yes	Title page and page i	EPA: No comments.
b. Date and revision number line (for when needed)	Yes	Title page and page i	EPA: Add a revision number line to the title and approval pages. Atlantic Richfield Response (6/7/21): Text added. EPA: Resolved. (6/16/21)
c. Indicates organization's name	Yes	Title page	EPA: No comments.
d. Date and signature line for organization's project manager	Yes	Page i	EPA: No comments.
e. Date and signature line for organization's QA manager	Yes	Page i	EPA: Add "Quality Assurance Approval Official" to Nikia Greene's signature line. Atlantic Richfield Response (6/7/21): Text added. EPA: Resolved. (6/16/21)
f. Other date and signatures lines, as needed	Yes	Page i	EPA: No comments.
A2. Table of Contents			•
a. Lists QA Project Plan information sections	Yes	Pages iii to vi	EPA: No comments.
b. Document control information indicated	Yes	Page v	EPA: No comments.
A3. Distribution List			
Includes all individuals who are to receive a copy of the QA Project Plan and identifies their organization	Yes	Page ii	EPA: No comments.
A4. Project/Task Organization			•
a. Identifies key individuals involved in all major aspects of the project, including contractors	Yes	Sections 2.0 through 2.3	EPA: The names of the key individuals need to be provided here in Sections 2.1 through 2.3 or, alternatively, in a new table. EPA realize periodically there will be personnel changes – these changes can be captured in the annual review and update of the QAPP. Atlantic Richfield Response (6/7/21): Sections 2.1 through 2.3
			Attantic Kichileid Response (6/7/21): Sections 2.1 through 2.5 address this requirement at the organization level. Specific names, titles, and project roles are provided in the revised RMAI Non-Residential Parcels QAPP. An updated organizational char is also provided in the revised QAPP Figure 2. EPA: Resolved. (6/16/21)
b. Discusses their responsibilities	Yes	Sections 2.0 through 2.3	EPA: No comments.

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

#### Page 5 of 28

c. Project QA Manager position indicates independence from unit generating data	Yes	Section 2.3, Figure 2	EPA: The QA manager was not specified. The responsibilities of the QA manager need to be added.
			Atlantic Richfield Response (6/7/21): Section 2.3 was revised to clearly identify the role of the Superfund Quality Assurance Manager. EPA: Resolved. (6/16/21)
d. Identifies individual responsible for maintaining the official, approved QA Project Plan	Yes	Section 2.3	EPA: The individual responsible for maintaining the official approved QAPP was not specified.
			Atlantic Richfield Response (6/7/21): Section 2.3 was revised to clearly identify that the BSB Department of Reclamation and Environmental Services Director is responsible for maintaining the official approved QAPP, and for ensuring that the work is performed in accordance with the requirements contained in the RMAP QAPP.
e. Organizational chart shows lines of authority and reporting responsibilities	Yes	Figure 2	EPA: Resolved. (6/16/21) EPA: The figure currently shows responsibilities extraneous to the RMAP program. An organizational chart specific only to the RMAP (with names) should be prepared. Additionally, other stakeholders should be depicted (such as AR, EPA/DEQ, QA Manager).
			Atlantic Richfield Response (6/7/21): A revised organizational chart is provided in Figure 2 of the QAPP.
A5. Problem Definition/Background			EPA: Resolved. (6/16/21)
a. States decision(s) to be made, actions to be taken, or outcomes expected from the information to be obtained	Yes	Sections 1.0 and 2.5 (formerly Section 2.4)	EPA: In Section 1.1, remove the two references to the Uniform Federal Policy for QAPPs (i.e., EPA 2005). This document is not in the format of a UFP-QAPP. Edit the reference section accordingly. Replace the second to last sentience of the first paragraph of Section 1.1 with: "This QAPP has been developed in accordance with the EPA Requirements for Quality Assurance Project Plans, EPA QA/R-5 (EPA 2001), the Guidance on Systematic Planning Using the Data Quality Objectives Process, EPA QA/G4 (EPA 2006), and the EPA Region 8 Quality Assurance Document Review Crosswalk checklist (EPA 2016)." In Section 2.4, modify the second sentence to read "",the soil sampling depth from 0 to 2 inches to the depth intervals provided in Section 3.2; changed the soil removal" The 0-2, 2-6, and 6-12 depth intervals are discussed in Sections 3.2.1 as well as 3.2.2.

			Atlantic Richfield Response (6/7/21): The requested modifications were made to Section 1.1 and Sections 2.5 (formerly Section 2.4). Section 1.1 was revised to "This QAPP has been developed in accordance with the EPA Requirements for Quality Assurance Project Plans, EPA QA/R-5 (EPA 2001), the Guidance on Systematic Planning Using the Data Quality Objectives Process, EPA QA/G4 (EPA 2006a), and the EPA Region 8 Quality Assurance Document Review Crosswalk checklist (EPA, 2016) provided in Attachment A."
			Section 2.5 (formerly Section 2.4 in previous version of the document) was revised to "This QAPP was developed in response to the EPA and Montana DEQ (the Agencies) 2006 Record of Decision (ROD) (EPA, 2006b) and Explanation of Significant Differences (ESD) to the 2006 Butte Priority Soils Operable Unit Record of Decision (EPA, 2011a). The ESD modified the soil sampling depth from 0 to 2 inches to the depth intervals provided in Section 3.2; changed the soil removal from a minimum depth of 18 inches to the minimum depth of 12 inches or to the soil bedrock interface if less than 12 inches; and extended the project schedule to accommodate expansion of the program."
b. Clearly explains the reason (site background or historical context) for initiating this project	Yes	Sections 2.5 & 2.6 (Formerly Sections 2.4 & 2.5)	EPA: No comments.
c. Identifies regulatory information, applicable criteria, action limits, etc. necessary to the project	Yes	Section 2.1	EPA: In Section 2.1, modify the last sentence to read: "The Agencies also review sampling results, including those above the action levels listed in Table 1, and project completion reports."
			Atlantic Richfield Response (6/7/21): Section 2.1 has been updated as requested. EPA: Resolved. (6/16/21)

**EPA Region 8 QA Document Review Crosswalk** BPSOU Draft Final Residential Metals Abatement Program (RMAP) OAPP (Non-Residential Parcels) (7/7/2021)

BPSOU Draft Final Residential Metals Abatement Program (RMA	- <u>```</u>		
a. Summarizes work to be performed, for example, measurements to be made, data files to be obtained, etc., that support the projects goals	Yes	Sections 1.0 and 2.6 (formerly Section 2.5)	<ul> <li>EPA: In the second paragraph of Section 1.0 and fourth paragraph of Section 2.5, add interior air monitoring for mercury vapor to the list of sampling tasks.</li> <li>Atlantic Richfield Response (6/7/21): Section 1.0 has been modified to state "The potential sources of lead, arsenic, and/or mercury exposure addressed in the Program include lead, arsenic, and mercury in yard soil and interior living space dust, lead in interior and/or exterior LBP and drinking water from pipe solder, mercury exposure through attic dust when exposure pathways are identified and/or earthen basement soil, and interior air monitoring for mercury vapor."</li> <li>Section 2.6 (formerly Section 2.5), fourth paragraph has been modified to state "The Program stipulates sampling residential soil, interior living space dust and attic dust for all COCs and interior air monitoring for mercury vapor within the BPSOU and by-request environmental sampling and remediation, if necessary, of residential properties outside of BPSOU, but within the 2020 RMAP</li> </ul>
			<i>Area shown in Figure 1</i> ". EPA: Resolved. (6/16/21)
b. Provides work schedule indicating critical project points, e.g., start and completion dates for activities such as sampling, analysis, data or file reviews, and assessments	Yes	Section 2.6 (formerly Section 2.5)	EPA: No comments.
c. Details geographical locations to be studied, including maps where possible	Yes	Sections 1.0 and 2.6 (formerly Section 2.5), Figure 1	EPA: No comments.
d. Discusses resource and time constraints, if applicable	Yes	Section 2.6.1 (formerly Section 2.5.1)	EPA: No comments.
A7. Quality Objectives and Criteria			

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

Page 8 of 28

BPSOU Draft Final Residential Metals Abatement Program (RM a. Identifies	No	Section 2.7.1	EPA: In Step 1, Table 1 specifies the analytical method for mercury
- performance/measurement criteria for all information		(formerly	vapor as "OSHA ID-140"; however, this method apples to the use of
to be collected and acceptance criteria for information		Section 2.6.1)	sorbent dosimeters analyzed by a laboratory, not a portable instrument
obtained from previous studies,			like the TRACKER-3000. If sorbent dosimeters are being utilized
- including project action limits and laboratory detection			(e.g., for confirmation measurements), this needs to be discussed
limits and			further in the QAPP. In Step 2, add study questions for the other types
- range of anticipated concentrations of each parameter			of sampling being conducted (e.g., mercury vapor in air, indoor dust, etc.). Also add text on what actions may result. A table with the study
of interest			questions and resulting actions may be a good way to provide this
			information. In Step 3, the text provides a good start describing the
			information inputs, but is incomplete. A summary of all the inputs
			needed to resolve the study questions in Step 2 is needed as well as
			text describing the use of input to resolve each study question. A table
			with the study question, the input to resolve the question, and the use
			of the input to resolve the question may be a good way to provide this
			information. In Step 4, more information on the vertical boundaries
			should be added, such as the highest point in a residential property and depths of sampling. The temporal boundaries of the investigation
			include the time from when evaluation and sampling actions begin at
			each property to the time specific clearance or completion criteria are
			met. In Step 5, a decision rule for mercury vapor needs to be added. In
			the third indented paragraph, specify the depth(s) of removal that may
			be implemented. Also in Steps 2 and 5, provide a definition and usage
			for the term "outdoor dust".
			Atlantic Richfield Response (6/7/21): Project DQOs have been
			revised per the guidelines provided in the Guidance on Systematic
			Planning Using the Data Quality Objectives Process (EPA QA/G-4)
			(Feb 2006) per Agency request. Additionally, the term "outdoor dust" is not applicable to the Program and has been removed.
			uust is not applicable to the i rogram and has been femoved.
			EPA: See comments on the revised DQOs provided in EPA's June 19,
			2021 comment memorandum. (6/19/21)
			Atlantic Richfield Response (7/2/21): Project DQOs have been updated per EPA's June 19, 2021 comment memorandum.
			EPA: Resolved. (7/8/21)

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

Page 9 of 28

b. Discusses precision	Yes	Sections 2.7.2	EPA: No comments.
b. Discusses precision	103	(formerly	LI A. NO comments.
		Section 2.6.2)	
		and Section	
		3.5.2	
		(formerly	
		Section 3.8.3)	
	<b>X</b> 7		
c. Addresses bias	Yes	Sections 2.7.2	EPA: No comments.
		(formerly	
		Section 2.6.2)	
		and Section 3.5.2	
		(formerly	
		Section 3.8.3)	
d. Discusses representativeness	Yes	Sections 2.7.2	EPA: It is not clear in the QAPP which soil samples will be analyzed
		(formerly	by XRF and those that will be analyzed by EPA standard laboratory
		Section 2.6.2)	methods. For example, here in Section 2.6.2 discussing
		and Section	representativeness it is stated that "in-place soils and backfill
		3.5.2	material will be analyzed by laboratory-grade XRF" However,
		(formerly	later in Section 3.8.1 it states that "analyses will be in accordance
		Section 3.8.3)	with the EPA analytical method specifications". Please clarify in
			the document when the different analytical methods will be used for
			soil analyses.
			Atlantic Richfield Response (6/7/21): The referenced text has
			been removed from Section 2.7.2 (formerly Section 2.6.2) in the revised document. Standard methods referenced in the document
			will be used.
			EPA: Resolved. (6/16/21)
- Identifies the need for some 1 to see	Vac	Section 272	
e. Identifies the need for completeness	Yes	Sections 2.7.2	EPA: No comments.
		(formerly	
		Section 2.6.2)	
		and Section	
		3.5.2	
		(formerly	
		Section 3.8.3)	

f. Describes the need for comparability	Yes	Sections 2.7.2 (formerly Section 2.6.2) and Section 3.5.2 (formerly Section 3.8.3)	EPA: No comments.
g. Discusses desired method sensitivity	No	Add to Section 2.7.2 (formerly Section 2.6.2)	EPA: Add a discussion regarding data sensitivity. For example, a discussion of the sensitivity of the TRACKER-3000 compared to the mercury vapor action level is needed.
			Atlantic Richfield Response (6/7/21): Sensitivity is related to the ability to compare analytical results with project-specific action levels. Analytical quantitation limits for the sample analytes should be below the level of interest to allow an effective comparison.
			Indoor assessments/sampling such as mercury vapor are not addressed under this version of the QAPP and will be addressed through forthcoming annual QAPP revisions. A mercury vapor method detection limit will be addressed at that time.
			EPA: Resolved. As EPA understands it, indoor mercury vapor investigations are usually only implemented if soil sample results indicate the presence of mercury. Because the focus of this QAPP is on exterior evaluations, no further modifications are necessary. However, the interior Non-Residential QAPP Amendment will need to document the process for mercury vapor investigation. (6/19/21)

PSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/72021)						
a. Identifies any project personnel specialized training or	Yes	Section 2.8	EPA: In the first paragraph, make sure it is clear that this is RMAP			
certifications		(Formerly	training. Note any special training requirements for use of the XRF			
		Section 2.7)	and/or mercury vapor analyzer. Also, all field personnel should have			
			HAZWOPER training.			
			Atlantic Richfield Response (6/7/21): Section 2.8 (formerly Section 2.7) has been updated as "All RMAP field personnel will review the requirements of this QAPP and receive training on Program-related tasks during a project meeting held prior to the beginning of fieldwork. A review of sampling procedures and requirements will be completed prior to field activities to ensure sample collection and handling methods are according to QAPP requirements. Field personnel will be trained in proper use of field equipment, sample collection tools, etc., and procedures according to field data collection SOPs (Attachment C-1) and methods described in the Program. Field personnel performing sampling activities or members who can potentially contact contaminated materials should receiver hazardous waste operations and emergency response (HAZWOPER) training." EPA: Resolved. (6/16/21)			
b. Discusses how this training will be provided	Yes	Section 2.8 (Formerly Section 2.7)	EPA: No comments.			

PSOU Draft Final Residential Metals Abatement Program (F c. Indicates personnel responsible for assuring training/certifications are satisfied	Yes	Section 2.8 (Formerly Section 2.7)	EPA: The personnel responsible for this element need to be identified. Atlantic Richfield Response (6/7/21): Section 2.8 (formerly Section 2.7), second paragraph has been updated to state "The BSB Department of Reclamation and Environmental Services Director is responsible for ensuring field personnel receive appropriate training and will maintain up-to-date training records and/or certifications. The BSB Department of Reclamation and Environmental Services Human Health/RMAP Division Manager will assure that each member of the sampling team obtains and is familiar with the recent version of the QAPP, will maintain signatures of each team member who has read the QAPP (including reviews and addenda, as necessary), and make sure each team member has been trained in the appropriate sample collection methods per the Program. The Human Health/RMAP Division Manager will review the SSHASP with all field personnel prior to fieldwork to assess the site's specific hazards and the control measurements that have been put in place to mitigate these hazards. The SSHASP review will also cover all other safety aspects of the site including site personnel responsibilities and contact information, additional site-specific safety requirements and
			procedures, and the emergency response plan." EPA: Resolved. (6/16/21)
d. identifies where this information is documented	Yes	Section 2.8 (Formerly Section 2.7)	EPA: No comments.
A9. Documentation and Records			
a. Identifies report format and summarizes all data report package information	Yes	Section 2.9 (formerly Section 2.8)	EPA: No comments.
b. Lists all other project documents, records, and electronic files that will be produced	Yes	Section 2.9 (formerly Section 2.8)	EPA: No comments.

BPSOU Drait Final Residential Metals Adatement Program (RM			
c. Identifies where project information should be kept	No	Section 2.9	EPA: Add text on how the project information described in Section
and for how long		(formerly	2.8 can be obtained, where it is being stored, and for how long.
		Section 2.8)	
			Atlantic Richfield Response (6/7/21): Section 2.9 (formerly Section 2.8) has been revised to the include additional details regarding project storage, backup and retention. All sampling data conducted for all media under the RMAP, including soils, attic dust, indoor dust and basement soils within the BPSOU and records of property access requests are housed within the RMAP database. The RMAP database is housed in an Access SQL server database and maintained by BSB. Document backups are contained in the BPSOU Document SharePoint and EPA document repository. Refer to the BPSOU Data Management Plan for additional details regarding data management, backup, and storage. EPA: Resolved. (6/16/21)
d. Discusses back up plans for records stored electronically	No	Section 2.9 (formerly Section 2.8)	EPA: Add more detail on how the data and information is backed up.
			Atlantic Richfield Response (6/7/21): Refer to response above.
			EPA: Resolved. (6/16/21)

Page 13 of 28

BPSOU Drait Final Residential Metals Adatement Program (RMA	Ar) QAPP (NOI	i-Residential Parc	CEIS) (////2021)
e. States how individuals identified in A3 will receive	No	Section 2.8	EPA: Clarify how the QAPP will be distributed and identify the
the most current copy of the approved QA Project Plan,		(formerly	individual responsible for this.
identifying the individual responsible for this		Section 2.7)	
			Atlantic Richfield Response (6/7/21): Atlantic Richfield will be responsible for distributing the original Agency approved QAPP to the individuals on the QAPP distribution list. Subsequent annual revisions will be distributed by the Butte Silver Bow Department of Reclamation and Environmental Services QA Manager. This is documented in text directly below the QAPP distribution list. Section 2.8 (formerly Section 2.7) has been revised to state "The BSB Department of Reclamation and Environmental Services Director is responsible for ensuring field personnel receive appropriate training and will maintain up-to-date training records and/or certifications. The BSB Department of Reclamation and Environmental Services Human Health/RMAP Division Manager will assure that each member of the sampling team obtains and is familiar with the recent version of the QAPP, will maintain signatures of each team member who has read the QAPP (including reviews and addenda, as necessary), and make sure each team member has been trained in the appropriate sample collection methods per the Program." EPA: Resolved. (6/16/21)
B. Data Generation/Acquisition			
<b>B1.</b> Sampling Process Design (Experimental Design)			

a. Describes and justifies design strategy, indicating size of the area, volume, or time period to be represented by a sample	Yes	Section 3.0	EPA: Given recent park sampling efforts in Anaconda, a fresh assessment of environmental conditions of all parks and play areas in the BPSOU and surrounding area is needed. A new section titled "Parks & Play Areas Sampling" needs to be added describing the compiling of existing park data, cataloguing response actions taken to date at parks and recreation sites, plans to fill data gaps with
			supplemental sampling, and the preparation of a data summary report for this sampling effort. Atlantic Richfield Response (6/7/21): Section 3.2 details the sampling plan for schools, parks, and non-residential daycares (which includes the delineation of the 5 land use categories). Existing park data will be reviewed but is not anticipated to be particularly useful for future remedial decision making due to current RMAP sampling guidelines (particularly current
			guidance around delineation of sampling polygons based upon land use categories). BSB will include cataloguing of action items in development of RMAP database. EPA: Resolved. (6/16/21)
b. Details the type and total number of sample types/matrix or test runs/trials expected and needed	Yes	Sections 3.2, 3.3, 3.4, and 3.5	EPA: No comments. Atlantic Richfield Response (6/7/21): Former sections 3.3 (attic and crawl spaces), 3.4 (interior dust sampling), and 3.5 (interior air monitoring) are not addressed in this version of the QAPP. They will be addressed through forthcoming annual QAPP revisions.

BPSOU Draft Final Residential Metals Abatement Program (RM	IAP) QAPP (NO	1	
c. Indicates where samples should be taken, how sites	Yes	Section 3.2.1	EPA: As originally stated in the BPSOU ROD, soil was to be sampled
will be identified/located			from the 0-2 inch depth interval, at a minimum. As modified in the
			2011 BPSOU ESD, the residential yard sampling described in Section
			3.2.1 calls for sampling from the 0-2 inch, 2-6 inch, and 6-12 inch
			depth intervals. EPA understands there may be properties where only
			the 0-2 inch depth interval was sampled in prior sampling and
			evaluation events. Please add text describing the identification of
			those properties where only 0-2 inch sampling has occurred and the
			plans to complete the sampling from the 2-6 and 6-12 inch depth
			intervals and taking appropriate follow-up action is action levels are
			exceeded.
			Atlantic Richfield Response (6/7/21): Section 3.2.3 (Previously Sampled Properties) has been added to address this sampling scenario. BSB will review the RMAP database to identify properties that were previously sampled to the 0-2 inch depth interval. Property owners of previously sampled properties where remediation was not completed will be contacted to request access to repeat the sampling to appropriate depth intervals. Sampling protocol described previously will be followed for the 2- 6 inch and 6-12 inch depth intervals.
			Properties that were sampled at the 0-2 inch depth interval and
			remediated will not be resampled.
			EPA: Resolved. (6/16/21)

**EPA Region 8 QA Document Review Crosswalk** BPSOU Draft Final Residential Metals Abatement Program (RMAP) OAPP (Non-Residential Parcels) (7/7/2021)

Page 17 of 28

PSOU Draft Final Residential Metals Abatement Program (RM d. Discusses what to do if sampling sites become	Yes	Section 3.1	EPA: This item refers to sampling sites that become inaccessible due,
inaccessible			for example, to weather conditions, etc. Physically, access is not an anticipated issue during the RMAP sampling. However, EPA understands there may be property owners who refuse to participate in the RMAP. The Agencies will assist AR and BSB in these cases. An addendum to the RMAP will be provided, describing the assistance that will be taken.
			Atlantic Richfield Response (6/7/21): Additional language has been included in Section 3.1 regarding three documented attempts to gain access, and a reset of attempts with a change in property ownership. "After three attempts are recorded, EPA and DEQ will be notified of the property status. At this time, EPA and/or DEQ may elect to issue the property owner an enforcement letter. A copy of the Agency notice form letter is provided in Attachment B-2. Future changes in ownership will be monitored annually. If ownership changes, the access procurement process will be re-initiated." EPA: Resolved. (6/16/21)
e. Identifies project activity schedules such as each sampling event, times samples should be sent to the laboratory, etc.	Yes	Sections 3.2, 3.3, 3.4, and 3.5	EPA: No comments. Atlantic Richfield Response (6/7/21): Former sections 3.3 (attic and crawl spaces), 3.4 (interior dust sampling), and 3.5 (interior air monitoring) are not addressed in this version of the QAPP. They will be addressed through forthcoming annual QAPP revisions.
f. Specifies what information is critical and what is for informational purposes only	Yes	Sections 3.2, 3.3, 3.4, and 3.5	EPA: No comments. Atlantic Richfield Response (6/7/21): Former sections 3.3 (attic and crawl spaces), 3.4 (interior dust sampling), and 3.5 (interior air monitoring) are not addressed in this version of the QAPP. They will be addressed through forthcoming annual QAPP revisions.
g. Identifies sources of variability and how this variability should be reconciled with project information	Yes	Step 6	EPA: No comments.
B2. Sampling Methods			

OU Draft Final Residential Metals Abatement Program (RM a. Identifies all sampling SOPs by number, date, and	Yes	Sections 3.3	EPA: As noted in comments in other recent documents, the CFRSSI
regulatory citation, indicating sampling options or modifications to be taken		and 3.4	SOPs cited are out of date and need updating. The cited SOP from the <i>Interior and Attic Dust Sampling and Analysis Plan</i> (Atlantic Richfield, 2007) must be attached to this QAPP. Alternatively, an SOP for dust sampling could be prepared. QAPPs are intended to be stand-alone documents with all sampling information contained therein. The first sentence of the second paragraph in Section 3.3 is confusing as there is not a CFRSSI SOP for attic dust sampling. In Section 3.4, the HVS3 manual should be attached to the QAPP.
			Atlantic Richfield Response (6/7/21): The appropriate SOPs have been included in the revised QAPP. EPA: Resolved. (6/16/21)
b. Indicates how each sample/matrix type should be collected	Yes	Sections 3.2, 3.3, 3.4, and 3.5	EPA: No comments. Atlantic Richfield Response (6/7/21): Former sections 3.3 (attic and crawl spaces), 3.4 (interior dust sampling), and 3.5 (interior air monitoring) are not addressed in this version of the QAPP. They will be addressed through forthcoming annual QAPP revisions.
c. If in situ monitoring, indicates how instruments should be deployed and operated to avoid contamination and ensure maintenance of proper data	NA	NA	EPA: No in-situ instruments will be deployed.
d. If continuous monitoring, indicates averaging time and how instruments should store and maintain raw data, or data averages	NA	NA	EPA: No continuous monitoring instruments will be deployed.
e. Indicates how samples are to be homogenized, composited, split, or filtered, if needed	Yes	Section 3.8.2	<ul> <li>EPA: Verify the sieve size needed for dust samples. Section 3.8.2 specifies a No. 18 sieve size, whereas the HVS3 method specifies and No. 100 sieve size.</li> <li>Atlantic Richfield Response (6/7/21): Former section 3.8.2 (Dust Analyses Methods has been removed from this QAPP. Interior assessments/sampling are not addressed in this version of the QAPP and will be addressed through forthcoming annual QAPP revisions.</li> <li>EPA: Resolved. (6/16/21)</li> </ul>

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

#### Page 19 of 28

f. Indicates what sample containers and sample volumes should be used	Yes	Sections 3.2, 3.3, 3.4, and 3.5	<ul> <li>EPA: In Section 3.6.1, please add the container type and sample volume requirement for the non-metals analysis.</li> <li>Atlantic Richfield Response (6/7/21): Former section 3.6.1 (Residential Lead Paint Sampling) has been removed from this QAPP. This initial version of the QAPP focuses solely on non-residential parcel soil sampling.</li> </ul>
g. Identifies whether samples should be preserved and indicates methods that should be followed	Yes	Section 3.6.2	<ul> <li>EPA: Resolved. (6/16/21)</li> <li>EPA: Regarding residential water sampling, add information to this section regarding the analytes to be requested (is it just lead?), bottle size required, and preservative.</li> <li>Atlantic Richfield Response (6/7/21): Former section 3.6.2 (Residential Water Sampling) has been removed from this QAPP. This initial version of the QAPP focuses solely on non-residential parcel soil sampling.</li> <li>EPA: Resolved. (6/16/21)</li> </ul>
h. Indicates whether sampling equipment and samplers should be cleaned and/or decontaminated, identifying how this should be done and by-products disposed of	Yes	Section 3.2.4, SOP G-8, Manuals	<ul> <li>EPA: No comments except suggest adding notes that sampling equipment (e.g., the HSV3) will be decontaminated per manufacturer requirements.</li> <li>Atlantic Richfield Response (6/7/21): Section 3.2.4 has been revised to include the following text "Re-usable equipment may be decontaminated between sampling sites in accordance with manufacturer's recommendations and established SOPs (Attachment C-1) and prior to being re-used."</li> <li>EPA: Resolved. (6/16/21)</li> </ul>
i. Identifies any equipment and support facilities needed	Yes	TBD	<ul> <li>EPA: Specify in the document where the sample preparation and XRF analytical work, if used, will be performed.</li> <li>Atlantic Richfield Response (6/7/21): This version of the QAPP deals solely with soil sampling. As detailed in Section 3.5.1, "All RMAP soil samples will be analyzed to determine metals concentrations via standard laboratory analytical methodologies for arsenic, lead, and mercury as appropriate." Interior assessments/sampling will be addressed through forthcoming annual QAPP revisions.</li> <li>EPA: Resolved. (6/16/21)</li> </ul>

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

1 500 Drait I mai Residentiai Metals Abatement i Togram (RM		in Residential I are	(11/2021)
j. Addresses actions to be taken when problems occur, identifying individual(s) responsible for corrective action and how this should be documented	Yes	Section 5.0	EPA: No comments.
B3. Sample Handling and Custody		•	•
a. States maximum holding times allowed from sample collection to extraction and/or analysis for each sample type and, for in-situ or continuous monitoring, the maximum time before retrieval of information	Yes	Section 3.3 (formerly Section 3.7.1)	EPA: No comments.
b. Identifies how samples or information should be physically handled, transported, and then received and held in the laboratory or office (including temperature upon receipt)	Yes	Section 3.3 (formerly Section 3.7.1)	EPA: No comments.
c. Indicates how sample or information handling and custody information should be documented, such as in field notebooks and forms, identifying individual responsible	Yes	Section 2.9.4 (formerly Section 2.8.4)	EPA: No comments.
d. Discusses system for identifying samples, for example, numbering system, sample tags and labels, and attaches forms to the plan	Yes	Section 3.4 (formerly Section 3.7)	EPA: No comments.
e. Identifies chain-of-custody procedures and includes form to track custody	Yes	Section 2.9.4 (formerly Section 2.8.4)	EPA: No comments.
B4. Analytical Methods		•	•
a. Identifies all analytical SOPs (field, laboratory and/or office) that should be followed by number, date, and regulatory citation, indicating options or modifications to be taken, such as sub-sampling and extraction procedures	Yes	Section 3.5 (formerly Section 3.8), Table 1, Attachment C (formerly Attachment 2), Former Attachment 3	<ul> <li>EPA: Table 1 needs to make clear which analytical method will be used to analyze soils (i.e., XRF or EPA Methodology). Additionally, Ashe Analytics should be removed as a laboratory services provider.</li> <li>Atlantic Richfield Response (6/7/21): Table 1 has been updated to reflect that EPA Methodology will be used to analyze all soil samples. Interior assessments/sampling will be addressed through forthcoming annual QAPP revisions.</li> </ul>
		Attachment 5	The revised OAPP does not include reference to Ashe Analytics.

(Manufacturer

Procedures) has been removed from this QAPP The revised QAPP does not include reference to Ashe Analytics.

EPA: Resolved. (6/16/21)

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

Page 21 of 28

b. Identifies equipment or instrumentation needed	Yes	Section 3.5 (formerly Section 3.8)	EPA: No comments.
c. Specifies any specific method performance criteria	Yes	Sections 2.7.2 (formerly Section 2.6.2) and Section 3.5.2 (formerly Section 3.8.3)	EPA: No comments.
d. Identifies procedures to follow when failures occur, identifying individual responsible for corrective action and appropriate documentation	Yes	Section 5.0	EPA: No comments.
e. Identifies sample disposal procedures	Yes	Section 3.7 (formerly Section 3.9)	EPA: No comments.
f. Specifies laboratory turnaround times needed	Yes	Section 5.3	EPA: No comments.
g. Provides method validation information and SOPs for nonstandard methods	Yes	Section 6.0	EPA: No comments.
B5. Quality Control			
a. For each type of sampling, analysis, or measurement technique, identifies QC activities which should be used, for example, blanks, spikes, duplicates, etc., and at what frequency	No	Sections 3.2, 3.3, 3.4, and 3.5	<ul> <li>EPA: Field QC measures and sampling (e.g., duplicates) for each type of sampling need to be discussed in these sections.</li> <li>Atlantic Richfield Response (6/7/21): Field duplicate samples are described in Section 3.6 in the revised QAPP.</li> </ul>
			Former sections 3.3 (attic and crawl spaces), 3.4 (interior dust sampling), and 3.5 (interior air monitoring) are not addressed in this version of the QAPP. They will be addressed through forthcoming annual QAPP revisions.
			EPA: See additional comments regarding field and laboratory QC provided in EPA's June 19, 2021 comment memorandum. (6/19/2021)
			Atlantic Richfield Response (7/2/21): Field and laboratory QC information has been updated per EPA's June 19, 2021 comment memorandum.

Page 22 of 28
---------------

b. Details what should be done when control limits are exceeded, and how effectiveness of control actions will be determined and documented	Yes	Section 5.0	EPA: No comments.
c. Identifies procedures and formulas for calculating applicable QC statistics, for example, for precision, bias, outliers and missing data	Yes	New section similar to Section 3.8.3	EPA: A new section similar to Section 3.8.3 discussing field QC activities and QC samples needs to be added. This new section needs to discuss, for example, field duplicate samples, the results of duplicate sampling, QC measurements during XRF paint analysis, results of decon blanks (e.g., after sieve decon), QC checks needed for the TRACKER-3000, etc.
			Atlantic Richfield Response (6/7/21): Section 3.6 Field Quality Control Samples has been added to the Revised QAPP.
			EPA: Resolved. (6/16/21)
B6. Instrument/Equipment Testing, Inspection, and Maint	enance		
a. Identifies field and laboratory equipment needing periodic maintenance, and the schedule for this	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
b. Identifies testing criteria	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
c. Notes availability and location of spare parts	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
d. Indicates procedures in place for inspecting equipment before usage	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
e. Identifies individual(s) responsible for testing, inspection and maintenance	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
f. Indicates how deficiencies found should be resolved, re-inspections performed, and effectiveness of corrective action determined and documented	Yes	Section 3.8 (formerly Section 3.10)	EPA: No comments.
<b>B7.</b> Instrument/Equipment Calibration and Frequency			

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

#### Page 23 of 28

should be calibrated and the frequency for this calibrationImage: Section 2, 7), 2,9,2 (former Section 2, 8,2), 3,8 (former Section 3, 10)b. Describes how calibrations should be performed and documented, indicating test criteria and standards or certified equipmentYesSections 2, 82, Section 2, 23, 2, 9,2 (former Section 2, 7), 2,9,2 (former Section 2, 8,2), 3,8 (former Section 3, 10)EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 3,9 (former Section 3,10)EPA: No comments.B. Inspection/Acceptance for Supplies and Consumables of criteria, and procedures for tracking, storing and criteria, and procedures for tracking, storing and criteria, and procedures for tracking, storing and criteria section 3,10)YesSection 3,9 (former Section 3,11)B. Use of Existing Data (Non-direct Measurements)YesSection 6,0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6,0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6,0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6,0EPA: No comments.c. Indicates the acceptance criteria of these data sources and/or modelsYesSection 6,0EPA: No comments.c. Indicates	a. Identifies equipment, tools, and instruments that	Yes	Sections 2.8	EPA: No comments.
calibrationSection 2.7), 2.9.2 (former Section 2.8.2), 3.8 (former documented, indicating test criteria and standards or certified equipmentYesSection 2.8.2), 3.8 (former Section 2.8.2), 3.8 (former Section 2.8.2), 3.8 (former Section 2.8.2), 3.8 (former Section 3.10)EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 3.0EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 3.0EPA: No comments.B. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.0EPA: No comments.a. Identifies critical supplies and consumables for field and haboratory, noting supply source, acceptance criteria, and procdures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data source and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.d. Identifies the inded use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria				
Section 2.8.2), 3.8 (former Section 3.10)Section 2.8.2), 3.8 (former Section 3.10)b. Describes how calibrations should be performed and documented, indicating test criteria and standards or certified equipmentYesSections 2.8 Section 2.8.2), 3.8 (former Section 3.10)EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.c. Identifies rotical supplies and ConsumablesYesSection 3.0EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for this accessed and usedYesSection 3.9 (former Section 3.11)EPA: No comments.B9. Use of Existing Data (Non-direct Measurements)YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed conditions should be determined, for example, internal and/or modelsYesSection 6.0EPA: No comments.	1 6		Section 2.7),	
13.8 (former Section 3.0)b. Describes how calibrations should be performed and documented, indicating test criteria and standards or certified equipmentYesSection 3.2.8 (former Section 2.7.), 2.9.3.8 (former Section 2.8.2.), 3.8 (former Section 3.10)EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 5.0 Section 3.00EPA: No comments.B. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for this accessed and usedYesSection 6.0 Section 3.11)EPA: No comments.B9. Use of Existing Data (Non-direct Measurements)YesSection 6.0 Section 3.11)EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0 Section 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0 Section 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comm			2.9.2 (former	
Image: constraint of the section of				
b. Describes how calibrations should be performed and documented, indicating test criteria and standards or certified equipmentYesSections 2.8 (former Section 2.7), 2.9.2 (former Section 3.10)EPA: No comments.c. Identifies how deficiencies should be resolved and documentedYesSection 3.0EPA: No comments.a. Identifies critical supplies and consumablesYesSection 3.10EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retriving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for this accessed and usedYesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed condition should be determined, for example, internal conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
documented, indicating test criteria and standards or certified equipment(former Section 2.7), 2.9.2 (former Section 2.8.2), 3.8 (former Section 3.20)c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments. <b>B8. Inspection/Acceptance for Supplies and Consumables</b> YesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments. <b>B9. Use of Existing Data (Non-direct Measurements)</b> YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies the individual do aperating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.			Section 3.10)	
certified equipmentSection 2.7), 2.9.2 (former Section 2.8.2), 3.8 (former Section 3.10)c. Identifies how deficiencies should be resolved and documentedYesSection 3.00c. Identifies ortical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)b. Identifies ortical supplies and consumables for this and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for this a latentifies or tilerature files, or models that should be accessed and usedYesSection 6.0 Section 6.0EPA: No comments.e. Identifies due use of this information and the rationale for their selection, i.e., its relevance to project c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0 Section 6.0EPA: No comments.d. Identifies the value of value of the information and the rationale for their selection, i.e., its relevance to project c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0 Section 6.0EPA: No comments.d. Identifies the value of value of the information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0 Section 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internal conditions should be determined, for example, internal <td></td> <td>Yes</td> <td>Sections 2.8</td> <td>EPA: No comments.</td>		Yes	Sections 2.8	EPA: No comments.
2.9.2 (former Section 2.8.2), 3.8 (former Section 3.10)2.9.2 (former Section 3.10)c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.B8. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to project c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies they resources/support facilities needed e. Describes how limits to validity and operating conditions should be determined, for example, internal conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
Section 2.8.2), 3.8 (former Section 3.10)Section 2.8.2), 3.8 (former Section 3.10)c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.B8. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments.B9. Use of Existing Data (Non-direct Measurements)YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed us nodelsYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed us nodelsYesSection 6.0EPA: No comments.c. Indicates the	certified equipment			
3.8 (former Section 3.10)c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.B8. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed us validity and operating conditions should be determined, for example, internal gendities neededYesSection 6.0EPA: No comments.				
Section 3.10)Section 3.10)c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.B8. Inspection/Acceptance for Supplies and ConsumablesYesSection 3.9 (former Section 3.11)EPA: No comments.a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments.B9. Use of Existing Data (Non-direct Measurements)YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed constructs should be determined, for example, internal conditions should be determined, for example, internalYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resource/support facilities needed conditions should be determined, for example, internalYes				
c. Identifies how deficiencies should be resolved and documentedYesSection 5.0EPA: No comments.B8. Inspection/Acceptance for Supplies and Consumablesa. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments. <b>B9. Use of Existing Data (Non-direct Measurements)</b> YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed accessed show limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
documentedImage: comparison of the compar			,	
a. Identifies critical supplies and consumables for field and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materialsYesSection 3.9 (former Section 3.11)EPA: No comments.b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments. <b>B9. Use of Existing Data (Non-direct Measurements)</b> YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed econdelsYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.		Yes	Section 5.0	EPA: No comments.
and laboratory, noting supply source, acceptance criteria, and procedures for tracking, storing and retrieving these materials(former Section 3.11)b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments. <b>B9. Use of Existing Data (Non-direct Measurements)</b> YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
criteria, and procedures for tracking, storing and retrieving these materialsSection 3.11)Section 3.11)b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments. <b>B9. Use of Existing Data (Non-direct Measurements)</b> A. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.		Yes		EPA: No comments.
retrieving these materialsImage: constraint of the section of the secti				
b. Identifies the individual(s) responsible for thisYesSection 3.9 (former Section 3.11)EPA: No comments.B9. Use of Existing Data (Non-direct Measurements)YesSection 6.0EPA: No comments.a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities needed e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.			Section 3.11)	
(former Section 3.11) <b>B9. Use of Existing Data (Non-direct Measurements)</b> a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
Section 3.11)B9. Use of Existing Data (Non-direct Measurements)a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.	b. Identifies the individual(s) responsible for this	Yes		EPA: No comments.
B9. Use of Existing Data (Non-direct Measurements)         a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and used       Yes       Section 6.0       EPA: No comments.         b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to project       Yes       Section 6.0       EPA: No comments.         c. Indicates the acceptance criteria for these data sources and/or models       Yes       Section 6.0       EPA: No comments.         d. Identifies key resources/support facilities needed       Yes       Section 6.0       EPA: No comments.         e. Describes how limits to validity and operating conditions should be determined, for example, internal       Yes       Section 6.0       EPA: No comments.			<b>`</b>	
a. Identifies data sources, for example, computer databases or literature files, or models that should be accessed and usedYesSection 6.0EPA: No comments.b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.			Section 3.11)	
databases or literature files, or models that should be accessed and usedaccessed and usedaccessed and usedb. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
accessed and usedImage: Constraint of the section of the		Yes	Section 6.0	EPA: No comments.
b. Describes the intended use of this information and the rationale for their selection, i.e., its relevance to projectYesSection 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
rationale for their selection, i.e., its relevance to projectImage: Section 6.0EPA: No comments.c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.				
c. Indicates the acceptance criteria for these data sources and/or modelsYesSection 6.0EPA: No comments.d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.		Yes	Section 6.0	EPA: No comments.
and/or modelsImage: Constraint of the second se	rationale for their selection, i.e., its relevance to project			
d. Identifies key resources/support facilities neededYesSection 6.0EPA: No comments.e. Describes how limits to validity and operating conditions should be determined, for example, internalYesSection 6.0EPA: No comments.		Yes	Section 6.0	EPA: No comments.
e. Describes how limits to validity and operating conditions should be determined, for example, internal Yes Section 6.0 EPA: No comments.	and/or models			
conditions should be determined, for example, internal	d. Identifies key resources/support facilities needed	Yes	Section 6.0	EPA: No comments.
		Yes	Section 6.0	EPA: No comments.
checks of the program and Beta testing				
B10. Data Management	B10. Data Management			

BPSOU Draft Final Residential Metals Abatement Program (RMAP) QAPP (Non-Residential Parcels) (7/7/2021)

Page 24 of 28

PSOU Draft Final Residential Metals Abatement Program (RN			, , , , , , , , , , , , , , , , , , , ,
a. Describes data management scheme from field to	Yes	Section 3.10	EPA: No comments.
final use and storage		(formerly	
		Section 3.12)	
b. Discusses standard record-keeping and tracking	Yes	Section 3.10	EPA: No comments.
practices, and the document control system or cites		(formerly	
other written documentation such as SOPs		Section 3.12)	
c. Identifies data handling equipment/procedures that	Yes	Section 3.10	EPA: No comments.
should be used to process, compile, analyze, and		(formerly	
transmit data reliably and accurately		Section 3.12)	
d. Identifies individual(s) responsible for this	Yes	Section 3.10	EPA: Add the individuals responsible for data management and/or
		(formerly	add text clarifying this in Section 2.3.
		Section 3.12)	
		, i i i i i i i i i i i i i i i i i i i	Atlantic Richfield Response (6/7/21): The Superfund Quality
			Assurance Manager has been identified as the responsible party
			for data management in Section 2.3.
			EPA: Resolved. (6/16/21)
		~	
e. Describes the process for data archival and retrieval	Yes	Section 3.10	EPA: Summarize the process where entities such as EPA can reques
		(formerly	or review data and information from the RMAP.
		Section 3.12)	
			Atlantic Richfield Response (6/7/21): Subsection 3.10.1 Requests
			for Data has been added to the revised QAPP.
			EPA: Resolved. (6/16/21)
f. Describes procedures to demonstrate acceptability of	Yes	Section 3.10	EPA: No comments.
hardware and software configurations		(formerly	
6		Section 3.12)	
g. Attaches checklists and forms that should be used	Yes	Section 3.10	EPA: Please provide a copy of the BSB Data Management Plan
	105	(formerly	(BSB, 2016) with the next submittal of this QAPP.
		Section 3.12)	
		,	Atlantic Richfield Response (6/7/21): The appropriate reference
			is Final Draft BPSOU Data Management Plan, Rev. 1 submitted
			12/22/2017.
			EPA: Resolved. (6/16/21)
C. Assessment and Oversight			
C1. Assessments and Response Actions			
a. Lists the number, frequency, and type of assessment	Yes	Section 5.0	EPA: No comments at this time.
activities that should be conducted, with the			
approximate dates			
approximate dates			

b. Identifies individual(s) responsible for conducting assessments, indicating their authority to issue stop work orders, and any other possible participants in the assessment process	Yes	Section 5.0	EPA: No comments at this time.		
c. Describes how and to whom assessment information should be reported	Yes	Section 5.1 and 5.2	EPA: No comments at this time.		
d. Identifies how corrective actions should be addressed and by whom, and how they should be verified and documented	Yes	Section 5.1 and 5.2	EPA: No comments at this time.		
C2. Reports to Management					
a. Identifies what project QA status reports are needed and how frequently	Yes	Section 5.3	EPA: No comments at this time.		
b. Identifies who should write these reports and who should receive this information	Yes	Section 5.3	EPA: No comments at this time.		
D. Data Validation and Usability					
D1. Data Review, Verification, and Validation					

BPSOU Draft Final Residential Metals Abatement Program (RM Describes criteria that should be used for accepting, rejecting, or qualifying project data	Yes	Section 6.0	<ul> <li>EPA: 1) There is reference made to the CFRSSI Data Management/Data Validation Plan Addendum (AERL 2000) in Section 6. It is EPA's understanding that this QAPP updates the validation process and is not following the older documents but developing an updated approach to validation while maintaining the critical elements of the previous historical documents. Clearly, it is time to update the 2000 DM/DV Plan and Pilot Data Report or take the steps needed to incorporate the necessary information from these documents into the BPSOU QMP and this QAPP.</li> <li>Atlantic Richfield Response (6/7/21): The critical elements of the CFRSSI documents, including the data validation checklists, Level AB assessment checklist, definitions of enforcement / screening / rejected data quality, and the data quality assessment process, have been included with the appropriate references in</li> </ul>
			the revised QAPP. All samples analyzed for metals at a commercial laboratory will be validated following the CFRSSI documents and the EPA National Functional Guidelines for Inorganic Superfund Methods Data Review, January 2017. EPA: Resolved. (6/16/21)
			2) Information needs to be provided on what level of quality the data needs to be that is being collected (enforcement versus screening).
			Atlantic Richfield Response (6/7/21): Section 6.0 has been modified to describe enforcement quality data. EPA: Resolved. (6/16/21)
			5) Update the reference for the EPA National Functional Guidelines to the current version: National Functional Guidelines for Inorganic Superfund Methods Data Review (January 2017).
			Atlantic Richfield Response (6/7/21): The EPA National Functional Guidelines has been updated as recommended. EPA: Resolved. (6/16/21)
			6) Update the reference for the EPA CLP SOW for Inorganic Superfund Methods from 2010 to the October 2016 version. The

BPSOU Draft Final Residential Metals Abatement Program (RM	AP) QAPP	(Non-Residential Pa	
			current ISM SOW is ISM02.4.
			Atlantic Richfield Response (6/7/21): The EPA CLP SOW for Inorganic Superfund Methods has been updated as recommended. EPA: Resolved. (6/16/21)
D2. Verification and Validation Methods		1	
a. Describes process for data verification and validation, providing SOPs and indicating what data validation software should be used, if any	Yes	Section 6.0	EPA: See applicable comments from D1. Atlantic Richfield Response (6/7/21): Section 6.0 has been updated. EPA: Resolved. (6/16/21)
b. Identifies who is responsible for verifying and validating different components of the project data/information, for example, chain-of-custody forms, receipt logs, calibration information, etc.	Yes	Section 6.0	EPA: See applicable comments from D1. Atlantic Richfield Response (6/7/21): Section 6.0 has been updated. EPA: Resolved. (6/16/21)
c. Identifies issue resolution process, and method and individual responsible for conveying these results to data users	Yes	Section 6.0	<ul> <li>EPA: See applicable comments from D1.</li> <li>Atlantic Richfield Response (6/7/21): Section 6.0 has been modified to describe responsibilities.</li> <li>EPA: Resolved. (6/16/21)</li> </ul>
d. Attaches checklists, forms, and calculations	Yes	Section 6.0	EPA: See applicable comments from D1. Atlantic Richfield Response (6/7/21): Section 6.0 has been updated. EPA: Resolved. (6/16/21)
D3. Reconciliation with User Requirements			
a. Describes procedures to evaluate the uncertainty of the validated data	Yes	Section 6.0	EPA: See applicable comments from D1. Atlantic Richfield Response (6/7/21): Section 6.0 has been updated. EPA: Resolved. (6/16/21)
b. Describes how limitations on data use should be reported to the data users	Yes	Section 6.0	EPA: See applicable comments from D1. Atlantic Richfield Response (6/7/21): Section 6.0 has been updated. EPA: Resolved. (6/16/21)