# Montana Tech Library Digital Commons @ Montana Tech

Silver Bow Creek/Butte Area Superfund Site

Montana Superfund

Fall 9-7-2021

Butte Priority Soils Operable Unit (BPSOU) Unreclaimed Sites – Final Field Sampling Plan (FSP) #2; Unreclaimed Sites UR-24, UR-26, and UR-40.

Mike McAnulty

Follow this and additional works at: https://digitalcommons.mtech.edu/superfund\_silverbowbutte Part of the Environmental Health and Protection Commons, Environmental Indicators and Impact Assessment Commons, and the Environmental Monitoring Commons

# **Atlantic Richfield Company**

Mike Mc Anulty Liability Manager 317 Anaconda Road Butte MT 59701 Direct (406) 782-9964 Fax (406) 782-9980

#### September 7, 2021

Nikia Greene Remedial Project Manager US EPA – Montana Office Baucus Federal Building 10 West 15th Street, Suite 3200 Helena, Montana 59626

Daryl Reed DEQ Project Officer P.O. Box 200901 Helena, Montana 59620-0901 Erin Agee Senior Assistant Regional Counsel US EPA Region 8 Office of Regional Counsel CERCLA Enforcement Section 1595 Wynkoop Street Denver, CO 80202 Mail Code: 80RC-C

Jonathan Morgan, Esq. DEQ, Legal Counsel P.O. Box 200901 Helena, Montana 59620-0901

# Butte Priority Soils Operable Unit (BPSOU) Unreclaimed Sites – Final Field Sampling Plan (FSP) #2; Unreclaimed Sites UR-24, UR-26, and UR-40.

Dear Agency Representatives:

The Final Field Sampling Plan (FSP) #2; Unreclaimed Sites UR-24, UR-26, and UR-40 is provided per the approval letter provided by the Agencies on August 27, 2021.

As described in Appendix D, Attachment C to the 2020 Consent Decree, areas listed as Unreclaimed Solid Media Sites within Butte Priority Soils Operable Unit (BPSOU) may have potentially been impacted by historic mining and therefore may pose a threat to human health, contribute metalsimpacted sediments to existing or planned wet weather control features, or contribute to the degradation of surface water quality. There are a total of 39 unclaimed sites, multiple sites will be organized in a package for approval. Field sampling plan (FSP) package #2 (FSP Package #2) includes Unreclaimed (UR) Sites UR-24, UR-26, and UR-40. Site evaluations will be performed using means and methods provided in the Atlantic Richfield Company Final UR Quality Assurance Project Plan (QAPP) published October 12, 2018, which was prepared in accordance with U.S. Environmental Protection Agency (EPA) guidance documents EPA QA/R-5 and EPA QA/G-5 for QAPP development. The QAPP was updated in 2021 (and is referred to herein as UR Sites QAPP) as a component of the BPSOU Solid Media Management Project Plan. Results from site evaluations will be used to prepare site declarations and assist with determination of site remediation requirements. Site evaluations will begin in 2021 and are anticipated to be completed in 2022, or as site access allows. Site declarations for sites sampled in 2021 are anticipated to be provided for Agency review and approval by the end of 2021. Declarations of sites sampled after 2021 will be provided as soon as



feasible. Remedial action will be performed following Agency approval of pertinent site-specific remedial action work plans.

A preliminary list of FSP packages, provided below, will be updated to record the status and progress related to FSP package submittals.

Package	Sites	Submittal Date	Approval Date
1	UR-31, 32, and 39	May 19, 2021	June 8, 2021
2	UR-24, 26, and 40	June 30, 2021	August 27, 2021
3	UR-06, 07, 20, 22, 35, and 36	July 2, 2021	August 27, 2021
4	UR-16 and 21	August 20, 2021	August 30, 2021
5	UR-12, 13, 33, and 38	August 23, 2021	August 30, 2021
6	UR-05, 27, 28, 29, 30, and 34	TBD	TBD
7	UR-01, 02, 03, 04, 15, and 17	TBD	TBD

The crosswalk list provided below references where pertinent field sample collection and documentation elements are discussed.

	Ref	erence Location
Element	FSP	UR Sites QAPP
Title page and approval authority.		Page i
Introduction and appropriate Agency-approved UR-Sites QAPP reference.	x	
Goals and objectives of sampling.		Section 2.4, 3.2
Proposed schedule for field work.	Х	
Site figure including sampling locations, number and depth of samples to be collected, and sample field identification.	x	Section 3.2.1
Field activity methods and procedures, standard operating procedures.		Section 3.2, Table 4
Sample labeling and shipping.		Section 3.2.5, Appendix C
Sample analysis, specifying X-ray fluorescence (XRF) vs. laboratory analysis and laboratory name.		Section 3.3
Figure showing the site and/or area represented by a sample, sample ID, and aliquot locations for composite samples.	х	

Soil sampling is proposed for FSP Package #2 at 3 UR Sites located in the south area of Butte, Montana, near the Copper Mountain Recreation Complex and Beef Trail. The results of the soil sampling will be used to support the site declaration and potential future remediation requirements for each site. This FSP is consistent with Section 3.0 Data Acquisition protocol described in the UR Sites QAPP. The UR Sites 24 and 26 are each less than 1.0 acre, UR-40 is 3.2 acres. UR-24 is located outside the complex fence, however debris protruding the ground presents hazards to children playing. UR-26 is a vacant lot with exposure potential to nearby residents. UR-40 is a vacant lot outside the fence of the complex that contains trails and residences nearby. Each of the sites is discussed separately below. The attachments at the end of this document include figures for each site showing the proposed soil sampling locations.

# Site: UR-24 Clark Mill and Adjacent Mill Tailings

# Background

Site UR-24 is approximately 0.7 acres. It is located within the Copper Mountain Recreation Park on Beef Trail Road (Figure 1). The site is part of an east-facing slope along an unnamed drainage west of the football fields and east of the driving range. The site has both areas with moderate vegetation and some significant bare areas. Many of the bare areas appear to have exposed mine waste. There is also metal debris and other garbage protruding through the ground within UR-24. This is the result of improperly covered garbage in the closed former Butte-Silver Bow landfill. Rilling has developed in some of the bare areas with fine-grained soils.

Site UR-24 is owned by Butte-Silver Bow. The nearest residence is about 1,300 feet south of Site UR-24 and higher in the drainage. There is fencing around the Copper Mountain Recreation Park but there is no fencing specifically around Site UR-24. Site UR-24 is in the Grove Gulch drainage basin of BPSOU.

# **Previous Sampling Efforts**

There is no record of previous soil sampling at this site or in the vicinity of UR-24.

# Site: UR-26 Grove Creek from Hanson to Rowe Rd

## Background

Site UR-26 is estimated at 0.37 acres. It is located just east of the intersection of South Montana Street, Beef Trail Road, and Hanson Road. From there, Site UR-26 trends northeasterly toward Rowe Road (Figure 2). Access to UR-26 is from Hanson Road or possibly from South Dakota Street.

The majority of Site UR-26 is owned by Kenneth and Margie Reap. A small portion of the site is owned by Butte-Silver Bow. Site UR-26 is vacant land that occupies the north bank of Grove Creek in a mostly residential part of Butte. The site has two piles of soil located in the northwest section; good grass cover has established along the walking path down the middle of the site that runs eastwest. Site UR-26 is in the Grove Gulch drainage basin of BPSOU and runoff from the site flows immediately into Grove Creek.

## **Previous Sampling Efforts**

Soil samples have been collected in the past at Site UR-26. Data obtained from the Geocortex webbased database at <u>https://eis2.woodardcurran.com/Html5Viewer/index.html?viewer=BPButte.BPSOU</u> contains the records for previous soil samples at or near Site UR-26. Approximate sample locations for the samples are included on Figure 2 with results provided in Table 1 below. Some of the samples listed show exceedances of BPSOU action levels for arsenic, lead, and zinc. The BPSOU action levels are listed in Tables 1 and 2 of the UR Sites QAPP.

(antes are mingrants per kitogrants)		
	Statio	on ID
COC	SO-GG-E	SO-GG-F
Arsenic	16	26
Cadmium	<4	<4
Copper	72 J	90 J
Lead	58	91
Zinc	200	574
Sample Date	11/3/97	11/3/97

## Table 1: Previous Sampling Results from BPSOU Soil Sampling (units are milligrams per kilograms)

COC: contaminants of concern.

# Site: UR-40 East Clark Mill Tailings

# Background

Site UR-40 (Source Area No. 155E) is approximately 3.2 acres located near east of the Copper Mountain Recreation Park. The site can be accessed from either South Montana Street or Beef Trail Road (Figure 3). The northern two-thirds of Site UR-40 consist of an abandoned railroad grade and the land surrounding it. The southern lobe of the site is near the bottom of a long, north-draining slope with the former Clark Mill at the top of the slope. Site UR-40 is owned by Butte-Silver Bow and is bounded on the north by a trucking firm and on the southeast by a residential neighborhood along South Montana Street. The nearest residence is about 100 feet due east of the east portion of Site UR-40. Parcels to the north and southeast of Site UR-40 are fenced, but there is not fencing that restricts access to UR-40. The fence along the east side of Copper Mountain Park does prevent direct access to UR-40 from the park.

The site has areas with both moderate vegetation and some significant bare areas. Some of the bare areas have white salts and black-stained gravel, which may be impacts from mine waste. Rilling has developed in some of the bare areas with fine-grained soils. Site UR-40 is in the Grove Gulch drainage basin.

# **Previous Sampling Efforts**

# Data obtained from the Geocortex web-based database at

<u>https://eis2.woodardcurran.com/Html5Viewer/index.html?viewer=BPButte.BPSOU</u> contains the records for previous soil sample locations at or near Site UR-40. Approximate sample locations are included on Figure 3 with results provided in Table 2 and Table 3 below. Two of these samples were from studies of former and current railroad beds within BPSOU. Some of the samples listed show

exceedances of BPSOU action levels for arsenic and zinc. The BPSOU action levels are listed in Tables 1 and 2 of the UR Sites QAPP.

	Sample Station ID		
COC	MTW010-00	RRNB012	FSUA-104
Arsenic	188	16	404
Cadmium	4	NA	NA
Copper	314 J	27	203
Lead	304	27	914
Zinc	1,030	100	2,000
Sample Date	5/16/91	6/10/93	12/14/95

#### Table 2: Previous Sampling Results from BPSOU Soil Sampling (units are milligrams per kilograms)

COC: contaminant of concern. NA: not analyzed.

In October 2005, Atlantic Richfield conducted soil sampling in the area surrounding the Clark Tailings and compiled the results into the Final Source Area Remedial Action Design Memorandum in 2007. The 2005 sampling was mostly to the south of UR-40 but did overlap slightly. The south lobe of UR-40 coincides with Sub-area 8 of the 2005 sampling event. The results for the Sub-area 8 samples (Clark8-uv and Clark8-v) are in Table 3. The samples were composites and collected from a depth of 0-2 inches. The results for the "Sub-area 8" samples do not exceed the BPSOU open space action levels for arsenic or lead, which is what they were being evaluated for at the time of that study. However, the results do exceed the storm water screening criteria for arsenic, lead, and zinc.

	Sample Station ID	
COC	Clark8-uv	Clark8-v
	(unvegetated)	(vegetated)
Arsenic	628	142
Cadmium	4.9	<3.9
Copper	367	153
Lead	1,110	201
Zinc	1,800	658
Sample Date	Oct. 2005	Oct. 2005

## Table 3: Previous Sampling Results from BPSOU Soil Sampling (units are milligrams per kilograms)

COC: contaminant of concern.

# **Unreclaimed Sites QAPP**

All field work and soil analysis will be completed in accordance with the UR Sites QAPP. The UR Sites QAPP will be reviewed annually and updated as needed on Agency review and approval. Soil sampling will be conducted at the 3 UR Sites at depth intervals of 6 to 12 inches, 2 to 6 inches, and 0 to 2 inches. Sampling will take place in that order from the deepest interval (6 to 12 inches) to the shallowest interval (0 to 2 inches). Proposed sample locations for each site are shown on Figures 1 through 3.

# **Sampling Procedure**

All sampling procedures are to be followed according to the UR Sites QAPP, which describes the activities necessary to conduct soil sampling and characterization activities on UR Sites within BPSOU. It also describes the quality assurance/quality control policies and procedures to be used during collection and analysis. Implementation of this fieldwork will likely commence in the spring of 2021, assuming that access has been obtained for all subject parcels.

If you have questions or comments, please do not hesitate to call me at (907) 355-3914.

Sincerely,

Mike Mednulty

Mike Mc Anulty Liability Manager Remediation Management Services Company An affiliate of **Atlantic Richfield Company** 

Attachments:


Figure 1 Unreclaimed Site UR-24 Proposed Sample Locations Figure 2 Unreclaimed Site UR-26 Proposed Sample Locations Figure 3 Unreclaimed Site UR-40 Proposed Sample Locations

Cc: Patricia Gallery / Atlantic Richfield - email Chris Greco / Atlantic Richfield – email Josh Bryson / Atlantic Richfield - email Mike Mc Anulty / Atlantic Richfield - email Loren Burmeister / Atlantic Richfield – email Dave Griffis / Atlantic Richfield - email Jean Martin / Atlantic Richfield - email Irene Montero / Atlantic Richfield - email David A. Gratson / Environmental Standards / email Mave Gasaway / DGS - email John Davis / PRR - email

Joe Vranka / EPA - email David Shanight / CDM - email Curt Coover / CDM - email James Freeman / DOJ - email John Sither / DOJ - email Jenny Chambers / DEQ - email Dave Bowers / DEQ - email Carolina Balliew / DEQ - email Matthew Dorrington / DEQ - email Jim Ford / NRDP - email Ray Vinkey / NRDP - email Harley Harris / NRDP - email Katherine Hausrath / NRDP - email Meranda Flugge / NRDP - email Ted Duaime / MBMG - email Gary Icopini / MBMG - email Becky Summerville / MR - email Kristen Stevens / UP - email Robert Bylsma / UP - email John Gilmour / Kelley Drye - email Leo Berry / BNSF - email Robert Lowry / BNSF - email Brooke Kuhl / BNSF – email Mark Engdahl / BNSF - email Jeremie Maehr / Kennedy Jenks - email Annika Silverman / Kennedy Jenks - email Matthew Mavrinac / RARUS - email Harrison Roughton / RARUS - email Brad Gordon / RARUS - email Mark Neary / BSB - email Eric Hassler / BSB - email Julia Crain / BSB - email Chad Anderson / BSB - email Brandon Warner / BSB – email Abigail Peltomaa / BSB - email Eileen Joyce / BSB – email Sean Peterson/BSB – email Gordon Hart / BSB – email Jeremy Grotbo / BSB – email Josh Vincent / WET - email Craig Deeney / TREC - email Scott Bradshaw / TREC - email Brad Archibald / Pioneer - email Pat Sampson / Pioneer - email Mike Borduin / Pioneer - email Joe McElroy / Pioneer – email

Andy Dare / Pioneer – email Karen Helfrich / Pioneer - email Leesla Jonart / Pioneer - email Connie Logan/ Pioneer – email Ian Magruder/ CTEC- email CTEC of Butte – email Scott Juskiewicz / Montana Tech – email

File: MiningSharePoint@bp.com - email BPSOU SharePoint - upload




8	3/13/2021 4:07:51 PM	Z:\SHARED\ACTIVE PROJECTS\	ARCO\UNRECLAIMEDSITES\C	ADD\FIGURES\UR24-FIG-001-21.DWG

COPPER MOUNTAIN PARK




SCALE IN FEET 20



÷	PROPOSED SOIL SAMPLE LOCATION

		DISPLAYED AS:
	COORD SYS/ZONE:	MSP
	DATUM:	NAD 83
	UNITS:	FEET
	SOURCE:	PIONEER
_		
		SCALE IN FEET
		20 40
	U U	20 40





#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8, MONTANA OFFICE

FEDERAL BUILDING, 10 West 15<sup>TH</sup> Street, Suite 3200 Helena, MT 59626-0096 Phone 866-457-2690 www.epa.gov/region8

Ref: 8MO

August 27, 2021

Mr. Mike McAnulty Liability Manager Atlantic Richfield Company 317 Anaconda Road Butte, Montana 59701

# Re: Approval letter for the Butte Priority Soils Operable Unit (BPSOU) Unreclaimed Sites Final Field Sampling Plan (FSP) Submittal #2: Unreclaimed Sites UR-21, UR-26, and UR-40 (dated August 18, 2021)

Dear Mike:

The U. S. Environmental Protection Agency (EPA), in consultation with the Montana Department of Environmental Quality (DEQ), is approving the *Unreclaimed (UR) Sites Final Field Sampling Plan (FSP) Submittal #2*. Please note that it is EPA's and DEQ's expectation that UR-26 site will be fully characterized, including an opportunistic sample(s) and sample(s) collected from waste/dredge piles that parallel the Grove Gulch stream. Please distribute this FSP submittal #2 as final.

If you have any questions or concerns, please call me at (406) 457-5019.

Sincerely,

NIKIA GREENE Digitally signed by NIKIA GREENE Date: 2021.08.27 09:40:57 -06'00'

Nikia Greene Remedial Project Manager

cc: (email only) Butte File Jenny Chambers; DEQ Matt Dorrington, DEQ Daryl Reed; DEQ Jon Morgan; DEQ counsel Carolina Balliew; DEQ Harley Harris; NRDP Katherine Hausrath: NRDP Jim Ford; NRDP Ray Vinkey; NRDP John Gallagher; BSBC Eileen Joyce; BSBC Sean Peterson; BSBC Eric Hassler: BSBC Brandon Warner; BSBC Chad Anderson: BSBC Karen Sullivan; BSBC Julia Crain: BSBC Abby Peltomaa; BSBC Jeremy Grotbo; BSBC Anne Walsh; UP Robert Bylsma; UP counsel Leo Berry; BNSF and UP counsel Mark Engdahl; BNSF Brooke Kuhl; BNSF counsel Jeremie Maehr; Kennedy Jenks for BNSF and UP Annika Silverman; Kennedy Jenks for BNSF and UP Bob Andreoli: Patroit/RARUS Becky Summerville; counsel for Inland Properties Inc. Robert Lowry, BNSF counsel Loren Burmeister; AR Josh Bryson; AR Mike Mcanulty; AR Dave Griffis: AR Jean Martin; Counsel AR Mave Gasaway; attorney for AR Adam Cohen; Counsel for AR Pat Sampson; Pioneer for AR Scott Bradshaw; TREC Mike Borduin: Pioneer for AR Karen Helfrich; Pioneer for AR Andy Dare; Pioneer for AR Scott Sampson; Pioneer for AR Brad Archibald; Pioneer for AR Andy Dare; Pioneer for AR Tina Donovan; Woodardcurran for AR Don Booth; AR consultant Ted Duaime; MBMG Gary Icopini; MBMG David Shanight, CDM Smith Curt Coover, CDM Smith Chapin Storrar; CDM Smith

Erin Agee, EPA Joe Vranka; EPA Chris Wardell; EPA Dana Barnicoat; EPA Charlie Partridge; EPA Jean Belille; EPA Ian Magruder; CTEC (Tech Advisor) Janice Hogan; CTEC Kristi Carroll; Montana Tech Library