

Montana Tech Library

Digital Commons @ Montana Tech

Silver Bow Creek/Butte Area Superfund Site

Montana Superfund

Summer 6-22-2022

**Butte Priority Soils Operable Unit (BPSOU) Draft Final Insufficiently Reclaimed Sites Field Sampling and Investigation Plan (FSP)
BRES No. 50 – Zelia**

Mike McAnulty

Follow this and additional works at: https://digitalcommons.mtech.edu/superfund_silverbowbutte



Part of the [Environmental Health and Protection Commons](#), [Environmental Indicators and Impact Assessment Commons](#), and the [Environmental Monitoring Commons](#)

June 22, 2022

Nikia Greene
Remedial Project Manager
US EPA – Montana Office
Baucus Federal Building
10 West 15th Street, Suite 3200
Helena, Montana 59626

Erin Agee
Senior Assistant Regional Counsel
US EPA Region 8 Office of Regional Counsel
CERCLA Enforcement Section
1595 Wynkoop Street
Denver, CO 80202
Mail Code: 8ORC-C

Daryl Reed
DEQ Project Officer
P.O. Box 200901
Helena, Montana 59620-0901

Jonathan Morgan, Esq.
DEQ, Legal Counsel
P.O. Box 200901
Helena, Montana 59620-0901

Re: Butte Priority Soils Operable Unit (BPSOU) Draft Final Insufficiently Reclaimed Sites Field Sampling and Investigation Plan (FSP) BRES No. 50 – Zelia

Dear Agency Representatives:

I am writing to you on behalf of Atlantic Richfield Company to submit the Butte Priority Soils Operable Unit (BPSOU) Draft Final Insufficiently Reclaimed (IR) Sites Field Sampling and Investigation Plan (FSP) Butte Remediation Evaluation System (BRES) No. 50 – Zelia.

As described in Appendix D, Attachment C to the 2020 BPSOU Consent Decree (CD) (available at <https://www.co.silverbow.mt.us/2161/ButtePriority-Soils-Operable-Unit-Conse>), sites listed as IR Solid Media Sites within the BPSOU were reclaimed prior to establishment of the Butte Hill Revegetation Specifications (BHRS), which is Appendix B of Appendix E to the U.S. Environmental Protection Agency (EPA) 2006 Record of Decision contained in the CD. Since additional reclamation work may be required to bring the sites into compliance with the BHRS, the sites will be evaluated to assess past actions and to identify any site-specific conditions that fail to meet the BHRS.

The site evaluation will include a review of available previous BRES field evaluations and site construction completion reports. It will also include an on-site evaluation. The site evaluation will include additional sampling performed according to the Atlantic Richfield Company *2022 Final Insufficiently Reclaimed Sites Quality Assurance Project Plan (QAPP)* (referred to as IR Sites QAPP). The IR Sites QAPP is available at the following link:

An updated [Link](#) will be provided upon approval of the 2022 IR QAPP¹, which was submitted to Agencies on May 20, 2022.

¹ Please note the link provided is valid for one year from the date of this submittal.

Field sampling within the existing boundary will be performed to determine whether contaminants are present, if growth media is adequate, and if there are previously unidentified sources contributing to site deficiencies.

Additional sampling performed in adjacent areas outside of the existing site boundary to characterize gap zones where site characterization may be unknown or incomplete will be conducted according to the Atlantic Richfield Company *Final Unreclaimed Sites Quality Assurance Project Plan* (referred to as the Unreclaimed Sites QAPP) which also is a component of the BPSOU Solid Media Management Project Plan and available at the following link:

<https://pioneertechnicalservices.sharepoint.com/:f:/s/submitted/Ev1dhUeMuUdLjU8tnuV5RioBvJZRYc2HpgEjM9KzT-PpjQ>².

Sample results in the areas outside of the existing site boundary will be evaluated to determine if contaminants are present beyond the site boundary at concentrations exceeding action levels listed in Table 1 or Table 2 in the Unreclaimed Sites QAPP. Final sampling data will be used to assist in determining the final site declaration.

This FSP provides details related to the field evaluation of the IR Site BRES No. 50 – Zelia. Proposed soil sampling stations and areas of known deficiencies are shown on Figure 1.

The site evaluation is anticipated to be completed in 2022. A site summary and declaration will be prepared to present all available site data and describe which BHRS criteria, if any, are not met. The site will be evaluated following the Recreational Land Use for IR Samples and Residential Land Use for UR Samples to evaluate Waste Identification and Action Level Criteria provided in the Insufficiently Reclaimed and Unreclaimed Sites QAPPs. A remedial action work plan (RAWP) describing actions that will be implemented at the site will be provided for Agency review and approval.

A list of FSPs, provided below, will be updated to record the status and progress related to FSP submittals.

Submittal	Site	Submittal Date	Approval Date	Sampling Complete
1	BRES No. 104 – Colorado Dump Shaft	9/29/2021	11/5/2021	-
1R	BRES No. 104 – Colorado Dump Shaft, Final Revised	12/2/2021	12/6/2021	2021
2	BRES No. 154 – Clark Mill Tailings NE	12/1/2021	12/6/2021	2021
3	BRES No. 30 – Atlantic-1	1/12/2022	2/22/2022	
4	BRES No. 16 – Curry	1/12/2022	2/22/2022	
5	BRES No. 8 – Belle of Butte	3/11/2022		
6	BRES No. 38 – Sister Dump	6/16/2022		
7	BRES No. 32 – Corra 2 Dumps	6/20/2022		

¹ Please note the link provided is valid for one year from the date of this submittal.

² Please note the link provided is valid for one year from the date of this submittal.

Submittal	Site	Submittal Date	Approval Date	Sampling Complete
8	BRES No. 158 – Waste Rock Dump	6/20/2022		
9	BRES No. 50 – Zelia	6/22/2022		

The crosswalk list provided below references where pertinent field sample collection and documentation elements are discussed.

Element	Reference Location		
	FSP	IR Sites QAPP	Unreclaimed Sites QAPP
Title page and approval authority.		Page i	Page i
Introduction and appropriate Agency-approved QAPP reference.	X		
Goals and objectives of sampling.		Section 2.4, Section 3.2	Section 2.4, Section 3.2
Proposed schedule for field work.	X		
Site figure including sampling locations, number and depth of samples to be collected, and sample field identification (ID).	X	Section 3.2.1	Section 3.2.1
Field activity methods and procedures, standard operating procedures.		Section 3.2, Table 4	Section 3.2, Table 4
Sample labeling and shipping.		Section 3.2.5, Appendix C	Section 3.2.5, Appendix C
Sample analysis specifying X-ray fluorescence vs. laboratory analysis and laboratory name.		Section 3.3	Section 3.3
Figure showing the site and/or area represented by a sample, sample ID, and aliquot locations for composite samples.	X		

Background

The Zelia site (BRES No. 50) is a 0.05-acre plot owned by Butte-Silver Bow and is located at the west end of Mullin Street. Reclamation was performed by ARCO in 1990 to 1991. Most of the mine waste was removed, and the area was sloped to match the surrounding topography. Lime rock from the Anaconda Quarry was applied at a rate of 350 tons per acre. Clean fill from the Minnie Irvine (BRES No. 1) borrow area was applied to a depth of 18 inches. A granular 11-52-0 fertilizer mix was dispersed at a rate of 300 pounds per acre. Following the application of the fertilizer, the area was chisel plowed, and the Walkerville EPA seed mixture was planted at a rate of 20 pounds per acre using a double disc drill seeder. Straw was then spread at a rate of 2 tons per acre.

Previous Evaluation Findings

The site was evaluated in 2017 during the recurring BRES site evaluation process. A review of previous site evaluations will be incorporated into the current site evaluation, sampling, and future remedial action. A preliminary review of the 2017 evaluation indicates issues with site edges. Site edges contained mostly knapweed and toadflax. Flow patterns, soil movement, plant pedestals, and litter were also observed along the sloped faces of the site.

Previous Sampling Efforts

Previous sampling has been conducted per the Residential Metals Abatement Program in the surrounding area. Residential sampling results may be available upon request.

Preliminary Site Evaluation

A preliminary site visit was conducted to qualify current site conditions and identify the focus areas for additional evaluation. Site photographs were taken during the preliminary site evaluation to capture site conditions. The photographs are included in this section for reference. The site consists of a barren parking area with gravel and fine material. Steep slopes appear to have bedrock outcropping throughout the slope. The site appears to exhibit weeds and undesirable species among native grasses throughout the barren areas and along the benches of the slopes. Small barren areas are located throughout the hillside, consistent with a rock outcropping.



Photograph 1: Steep Slopes and Parking Area



Photograph 2: Parking Area with Vehicle Traffic



Photograph 3: Barren Area near Residential lot



Photograph 4: Fine Material and Sediment throughout Barren Area

Site Characterization Plan

Per the IR Sites QAPP, the site will be sampled at 2 depth intervals [(1) 0 to 6 inches and (2) 6 to 18 inches] to determine whether mining related waste is present and/or confirm the depth of previous reclamation efforts. Additional samples obtained outside of the existing site boundary will be obtained from 3 depth intervals [(3) 0 to 2 inches, (4) 2 to 6 inches, and (5) 6 to 12 inches] per the Unreclaimed Sites QAPP sampling protocol. Figure 1 illustrates the proposed sample stations.

Opportunistic samples may be obtained in the field at the discretion of field sampling personnel or Agency oversight representative(s). The field team leader will be responsible for determining the appropriate sampling protocol as dictated by the location of the opportunistic sample(s).

Results will be used to prepare the site declaration and prescribe site remedial improvements. The overall site will be sampled following procedures in the IR Sites QAPP using a systematic procedure to determine the spatial characterization of waste, parameters of previous reclamation, and extent of transient material. Sampling performed outside of the existing boundary will be used to determine if waste extends beyond the existing boundary at concentrations which exceed levels listed in Table 1 or Table 2 of the Unreclaimed Sites QAPP and will be used to assist in the determination of the final site declaration.

Existing site grading and drainages will be evaluated to determine storm water flow patterns and identify if additional storm water controls will help prevent sediment migration. The location and condition of existing storm water features will be field-verified and recorded to be used in corrective actions. Contributing sources of storm water upgradient and adjacent to the site will also be investigated.

Items identified below will be evaluated to determine whether they are adequate and to identify if additional remedial measures are necessary. The following provides the minimum potential site characterization items to consider. Additional items may be identified during the remedial design process.

- Investigate controlled site access requirements.
- Evaluate plant species cover to BHRS seed mix specifications.
 - Coordinate and confirm plant species with biology/plant ecologist or related subject matter expert.
- Evaluate potential site storm water controls to mitigate run-on/runoff.
- Identify remedial improvements to mitigate site erosion and vegetative areas to meet BHRS.
- Identify maintenance items for successful long-term operation.

Final remedial cap configuration (i.e., vegetative or engineered) will be coordinated with the landowner's end usage. A final RAWP will be provided for Agency review and approval.

Sampling Procedure

All soil sampling and characterization activities and procedures within the existing site boundary from the sample stations listed below will follow the IR Sites QAPP. The IR Sites QAPP also describes the quality assurance/quality control policies and procedures that will be used during sample collection and analysis.

Sample Station	2 Depth Intervals (inches)
IR-50-SS01	(1) 0-6, (2) 6-18
IR-50-SS02	(1) 0-6, (2) 6-18
IR-50-SS03	(1) 0-6, (2) 6-18

All soil sampling and characterization activities beyond the existing site boundary at sample stations listed below will follow the Unreclaimed Sites QAPP.

Sample Station	3 Depth Intervals (inches)
IR-50-SS04	(3) 0-2, (4) 2-6, and (5) 6-12
IR-50-SS05	(3) 0-2, (4) 2-6, and (5) 6-12
IR-50-SS06	(3) 0-2, (4) 2-6, and (5) 6-12

Fieldwork is anticipated to begin in summer of 2022.

Site Summary Report and Declaration

After the site evaluation and data collection activities have been completed, a summary report will be prepared and submitted to Agencies for review and approval. The report will include a summary of all available site sampling data and a site declaration specifying any deficient BHRS criteria.

If you have questions or comments, please do not hesitate to call me at (907) 355-3914.

Sincerely,



Mike Mc Anulty
 Liability Manager
 Remediation Management Services Company
 An affiliate of **Atlantic Richfield Company**

Attachments:

- Figure 1 – Insufficiently Reclaimed Sites BRES No. 50 Zelia Proposed Sample Stations
- Attachment 1: Document Links

- Cc: Patricia Gallery / Atlantic Richfield - email
 Chris Greco / Atlantic Richfield – email
 Josh Bryson / Atlantic Richfield - email
 Mike Mc Anulty / Atlantic Richfield - email
 Loren Burmeister / Atlantic Richfield – email
 Dave Griffis / Atlantic Richfield - email
 Jean Martin / Atlantic Richfield - email
 Irene Montero / Atlantic Richfield - email

David A. Gratson / Environmental Standards / email
Mave Gasaway / DGS - email
Brienne McClafferty / Holland & Hart - email
Joe Vranka / EPA - email
David Shanight / CDM - email
Curt Coover / CDM - email
James Freeman / DOJ - email
John Sither / DOJ - email
Dave Bowers / DEQ - email
Carolina Balliew / DEQ - email
Matthew Dorrington / DEQ – email
Wil George / DEQ – email
Jim Ford / NRDP - email
Pat Cunneen / NRDP - email
Harley Harris / NRDP - email
Katherine Hausrath / NRDP - email
Meranda Flugge / NRDP - email
Ted Duaine / MBMG - email
Gary Icopini / MBMG - email
Becky Summerville / MR - email
Kristen Stevens / UP - email
Robert Bylsma / UP - email
John Gilmour / Kelley Drye - email
Leo Berry / BNSF - email
Robert Lowry / BNSF - email
Brooke Kuhl / BNSF – email
Lauren Knickrehm / BNSF - email
Jeremie Maehr / Kennedy Jenks - email
Annika Silverman / Kennedy Jenks - email
Matthew Mavrinac / RARUS - email
Harrison Roughton / RARUS - email
Brad Gordon / RARUS - email
Mark Neary / BSB - email
Eric Hassler / BSB - email
Julia Crain / BSB - email
Chad Anderson / BSB - email
Brandon Warner / BSB – email
Abigail Peltomaa / BSB - email
Eileen Joyce / BSB – email
Sean Peterson/BSB – email
Gordon Hart / BSB – email
Jeremy Grotbo / BSB – email
Karen Maloughney / BSB – email
Josh Vincent / WET - email
Craig Deeney / TREC - email
Scott Bradshaw / TREC - email

Brad Archibald / Pioneer - email
Pat Sampson / Pioneer - email
Joe McElroy / Pioneer – email
Andy Dare / Pioneer – email
Karen Helfrich / Pioneer - email
Leesla Jonart / Pioneer - email
Randa Colling / Pioneer – email
Ian Magruder/ CTEC- email
CTEC of Butte – email
Scott Juskiewicz / Montana Tech – email

File: MiningSharePoint@bp.com - email
BPSOU SharePoint – upload

Figures


Figure 1 – Insufficiently Reclaimed Sites IR-50 Zelia Proposed Sample Stations



LEGEND

- SAMPLE UNDER IR QAPP
- SAMPLE UNDER UR QAPP
- INSUFFICIENTLY RECLAIMED AREA
- PROPOSED IR BOUNDARY CHANGES
- PROPERTY OWNERSHIP
- S — STORM WATER LINE

THE PARCEL BOUNDARIES SHOWN ARE FOR REFERENCE USE ONLY AND DO NOT REPRESENT A LEGAL SURVEY



DISPLAYED AS: _____
 PROJECTION/ZONE: MSP
 DATUM: NAD 83
 UNITS: INT'L FT
 SOURCE: PIONEER/BSB/AR/QSI 2020

0 10 20 40
Feet

FIGURE 1

INSUFFICIENTLY RECLAIMED
SITES BRES No. 50 ZELIA
PROPOSED SAMPLE STATIONS

DATE: 3/4/2022

Attachment 1
Document Links

Document Links

Insufficiently Reclaimed Sites QAPP:

An updated [Link](#) will be provided upon approval of the 2022 IR QAPP³, which was submitted to Agencies on May 20, 2022.

Unreclaimed Sites QAPP:

<https://pioneertechnicalservices.sharepoint.com/:f/s/submitted/Ev1dhUeMuUdLjU8tnuV5RioBvJZRYc2HpgEjM9KzT-PpjQ>⁴.

³ Please note the link provided is valid for one year from the date of this submittal.

⁴ Please note the link provided is valid for one year from the date of this submittal.